Newmarket 127/097

Date of Inspection:	07/14/2011	NH108
Date Report Sent:	Not Sent Yet	Over
Picture taken dur	ing inspection	LAMPREY RIVER
Owner: NHDOT		Newmarket Veterans Bridge

Recommended Postings:

✓ Weight Sign OK Weight: No Posting Required

✓ Width Sign OK Width: Not Required

Clearances: Over: ✓ Height Signs OK Primary Height Sign Recommendation: None

(Feet) Under: 0.00 Optional Centerline Height Sign Rec: None

Route:

Condition: Not on the Redlist **Structure Type and Materials:**

Number of Spans Main Unit: 1 Deck: 5 Fair Number of Approach Spans: 0 Superstructure: 6 Satisfactory

Substructure: 6 Satisfactory Main Span Material and Design Type Culvert: N N/A (NBI)

Steel Multiple Beam

Sufficiency Rating: 74.3%

NBI Status: Functionally Obsolete

Bridge Rail: Meets Standards NH Bridge Type: I Beams w/ Concrete Deck Deck Type: Concrete, Cast in Place Rail Transition: Meets Standards

Bridge Approach Rail: Substandard Wearing Surface: Bituminous Approach Rail Ends: Substandard Membrane: None Deck Protection: None Pavement thickness: 3.0 in

Curb Reveal: Not Applicable

Plan Location: 3-3-4-1 **Bridge Dimensions:**

Length Maximum Span: 61.0 ft Total Bridge Length: 66.0 ft Left Curb/Sidewalk Width: 0.3 ft Right Curb/Sidewalk Width: 5.5 ft Width Curb to Curb: 28.0 ft Total Bridge Width: 35.0 ft Approach Roadway Width (W/ Shoulders): 30.0 ft Median: No median

Bridge Skew: 22.00 °

Bridge Service:

Type of Service on Bridge: Highway and Pedestrian Year Built: 1955 Type of Service under: Waterway Year Rebuilt: Not Rebuilt Lanes on bridge: 2 Detour Length: 4.0 mi

Lanes Under: NA

AADT: 12000 Percent Trucks: 4% Year of AADT: 2007 Future AADT: 17760 Year of Future AADT: 2032

Federal or State Definition Bridge: Fed. Definition Bridge
Roadway Functional Class: Rural Mjr. Collector

New Hampshire Highway System and Class: Primary-DOT Maintained

Eligibility for the National Register of Historic Places: Possibly eligible Traffic Direction: Two-way traffic

National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: Intolerable, Replacement Underclearances: Not Applicable (NBI)
Approach Alignment: Equal Minimum Criteria
Structural Evaluation: Equal Minimum Criteria

Channel/Channel Protection: Protected

Waterway Adequacy: Equal Desirable Criteria Bridge Scour Critical Status: Stable for extreme flood

Riprap Condition: Good Condition

Debris Present: No Debris Present

DAM DOWNSTREAM OPEN 11/5/09.

Date of Underwater Inspection: Jul. 2011

AASHTO CoRe Element Condition State Data:

No.	Description	Env.	Material Notes and Condition Notes
13	Concrete Deck -	Moderate	
	Unprotected, with Asphalt Pavement	ASPHALT NE	W.
107	Painted Steel Beam or Girder (Open Web)	Moderate	
		NEW PAINT.	OLD SECTION LOSS. MINOR LEAKING.
217 Other Material		Moderate	
	Abutment	VOIDS, CRAC	CKED STONE, SETTLED. CONCRETE- CRACKS IN CONCRETE CAP.
303	Modular Joint and Seal	Moderate	Steel Sliding Plate.
	Assembly	PAVED OVER	R NOT VISIBLE.
311	Moveable Bearing (roller, sliding, etc.)	Moderate	
		< none >	
313	Fixed Bearing	Moderate	
		< none >	
330	Uncoated Metal Bridge	Benign	
	Railing	PLOW DAMA	GE.

Newmarket 127/097

No.	Description	Env.	Material Notes and Condition Notes
359	Soffit of Conc Deck or Slab Condition Warning Flag	Moderate	
		LIGHT CRAC	CKS AND LEAKING, DELAMINATION. REPAIRED DECK AT EXTERIORS.
361	Scour Condition	Moderate	Element record added 2010-07-13.
	Warning Flag	VOIDS IN ST	TONES. DAM DOWNSTREAM.

No.	Description	Env.	Quantity	Units	State 1	State 2	State 3	State 4	State 5
13	Concrete Deck - Unprotected, with Asph	Moderate	2,400	(SF)	0 %	100 %	0 %	0 %	0 %
107	Painted Steel Beam or Girder (Open We	Moderate	397	(LF)	16 %	84 %	0 %	0 %	0 %
217	Other Material Abutment	Moderate	112	(LF)	0 %	95 %	5 %	0 %	
303	Modular Joint and Seal Assembly	Moderate	36	(LF)	90 %	10 %	0 %		
311	Moveable Bearing (roller, sliding, etc.)	Moderate	6	(EA)	16 %	84 %	0 %		
313	Fixed Bearing	Moderate	6	(EA)	0 %	100 %	0 %		
330	Uncoated Metal Bridge Railing	Benign	240	(LF)	99 %	0 %	0 %	1 %	
359	Soffit of Conc Deck or Slab Condition W	Moderate	1	(EA)	0 %	100 %	0 %	0 %	0 %
361	Scour Condition Warning Flag	Moderate	1	(EA)	100 %	0 %	0 %		

Bridge Notes:

NEW CURBS, WINGS, CONCRETE CAPS, SIDEWALKS AND RAIL, BY B.O.B.M. (2001)

"Newmarket Veterans Bridge" (Chapter 213, 2006 NH Laws (SB 239)) Approach and Roadway Notes: ASPHALT-NEW . ALUMINUM RAIL OK.

Unusual or experimental features: Not visible

Inspection History:

Inspection Date: 07/14/2011 Inspector: JEL Deck: 5 Fair Super: 6 Satisfactory ****underwater inspection**** Substr: 6 Satisfactory JEL UNDERWATER INSPECTION COMMENTS-Culvert: N N/A (NBI) SUBSTRUCTURE- THE SUBMERGED PORTIONS OF SUBSTRUCTURE ARE INE SATISFACTORY CONDITION WITH NO SIGNIFICANT DEFECTS. ONE VOID WAS OBSERVED NEAR SOUTH END OF WEST ABUTMENT AT THE STREAM BOTTOM(MASONRY UNIT MAY HAVE BEEN DISPLACED SINCE LAST INSPECTION). AREA ON BACKSIDE OF VOID APPEARED SOLID. THE MASONRY UNITS ARE DRY SET. APPROXIMATELY 40% OF CHINK STONES ARE MISSING. A PORTION OF THE FOOTING ON THE EAST ABUTMENT IS VISIBLE (DRY SET STONE). RIVER BOTTOM IS BEDROCK WITH COBBLES.

Inspection Date: 07/13/2010 Inspector: KJT Deck: 5 Fair Notes: Super: 6 Satisfactory

Substr: 6 Satisfactory KJT inspection comments -DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK. Culvert: N N/A (NBI) SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. NEW CONCRETE CAPS

AND WINGS. VOIDS CRACKED STONES SETTLED.

Inspection History:

Inspection Date: 11/05/2009 Inspector: DPC Deck: 5 Fair

Super: 6 Satisfactory Notes: DPC-inspection comments -Substr: 6 Satisfactory

DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK. Culvert: N N/A (NBI) SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION.

SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. NEW CONCRETE CAPS AND WINGS.

PICTURES: C407

#19: VOIDS IN NORTH WEST WING. #20: VOIDS IN NORTH ABUTMENT.

#21: SOUTH WEST WING - VOIDS AND BULGING.

#22: SOUTH ABUTMENT - VOIDS. #23: VOIDS IN SOUTH EAST WING. #24: VOIDS IN NORTH EAST WING.

Inspection Date: 05/01/2008 Inspector: KJT Deck: 5 Fair

Super: 6 Satisfactory Notes: KJT-inspection comments -Substr: 6 Satisfactory DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK.

Culvert: N N/A (NBI) SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION.

SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. NEW CONCRETE CAPS

AND WINGS.

Inspection Date: 05/23/2006 Deck: 5 Fair Inspector: RLM

Notes: Super: 6 Satisfactory Substr: 6 Satisfactory RLM inspection comments -DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK.

Culvert: N N/A (NBI) SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION.

SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. NEW CONCRETE CAPS

AND WINGS.

Inspection Date: 07/02/2004 Inspector: RLM Deck: 5 Fair

Super: 6 Satisfactory Notes: Sufficiency Rating Calculation Accepted by DMB at 8/26/2005 14:26:47 Substr: 6 Satisfactory

RLM inspection comments -Culvert: N N/A (NBI) DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK. SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION.

SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDI

Inspection Date: 04/15/2002 Inspector: DPC Deck: 5 Fair Notes: Super: 6 Satisfactory Sufficiency Rating Calculation Accepted by DEP at 10/14/2002 15:52:13 Substr: 6 Satisfactory

DPC inspection comments -Culvert: N N/A (NBI) DECK- ELEMENTS IN FAIR CONDITION. NEW CURBS AND SIDEWALK.

SUPERSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION. NEW CONCRETE CAPS

AND WINGS.

PIC: C135-17, 18, 19

Inspection Date: 05/03/2000 Inspector: DPC Deck: 5 Fair

Super: 6 Satisfactory Notes: Sufficiency Rating Calculation Accepted by DEP at 10-16-2000 14:35:25 Substr: 5 Fair

DPC inspection comments -

Culvert: N N/A (NBI) DECK - ELEMENTS IN FAIR CONDITION. CURB UPSTREAM IN SERIOUS CONDITION. SUPERSTRUCTURE - ELEMENTS IN SATISFACTORY CONDITION.

SUBSTRUCTURE - ELEMENTS IN FAIR CONDITION. WINGS IN POOR CONDITION. APPROACH BRIDGESEAT IN POOR CONDITION AT UPSTREAM.

Newmarket 127/097

Bridge Inspection Report

Inspection History:

FNM inspection of leaking overall, for spalled with rebar	g Calculation Accepted by omments- Deck: cracked ew delaminations. Mediu	Inspector: FNM DEP at 12-23-98 08:09:39 I and heavily spalled at the west curb/deck edge, light crack at deck/sidewalk joint at east. Curbs head dewalk: light cracks heavy leaking at the east deck	Super: Substr: Culvert: ght avily	5 Fair 7 Good 5 Fair N N/A (NBI)	
the SE. Bridgese	ncrete capped- cracked s	tone with voids, settled. Concrete -medium spallin WW approach beam. Medium spall at the SE. Wing ed, settled.			
Inspection Date: Notes:	06/01/1996	Inspector: Not Available	Super: Substr:	6 Satisfactory 7 Good 5 Fair N N/A (NBI)	
Inspection Date: Notes:	06/01/1994	Inspector: Not Available	Super: Substr:	6 Satisfactory 7 Good 6 Satisfactory N N/A (NBI)	
Inspection Date: Notes:	07/01/1992	Inspector: Not Available	Super: Substr:	6 Satisfactory 8 Very Good 6 Satisfactory N N/A (NBI)	
= ` '	Municipal Hghways Municipal Hghways	Border State Bureau of Rail and Transit Army Corps Of Engineers Railroad	= '		

































